



Herriman & Associates, Inc.

COMMUNITY ASSOCIATION MANAGERS

41486 Wilcox Road • Plymouth, MI 48170-3104

734 459-5440 • Fax 734 459-0690

www.herriman.net

July 17, 2014

RE: CHV Catch Basin Repairs

Dear Cherry Hill Village Resident:

This communication is to alert residents that catch basin repairs will be performed throughout CHV in the upcoming weeks. The majority of the repairs will be in the alleys. We ask you to please be cautious in these areas when leaving and returning to your residence. When leaving and returning, you may have to use the other end of the alley to access your home. There may be a few units that might have to park in the street if a catch basin is blocking the access to your drive.

The process will most likely be a three day process; with saw cutting the asphalt first, removing the asphalt second and catch basins being repaired and then the cut out area replaced with concrete (weather permitting). The concrete cure time is seven days before any vehicle may drive on it; construction barrels will be placed around that area during the cure time.

We will send out another communication when we have a starting date. Please check map for catch basin locations.

We apologize for any inconvenience.

Thank you for your cooperation,

Jeff McDuff, Site Manager
Cherry Hill Village
Herriman & Associates, Inc.
Management Agent for
Cherry Hill Village
734-495-0505
jmcduff@herriman.net